



## Premium Tech Tool Compatible Adapter Matrix

### For Premium Tech Tool 2.8

*(Drivers and Firmware versions are compatible with Tech Tool version 2.8.121 and newer)*

Click on your respective brand below for the corresponding compatible adapter matrix

[Mack Trucks](#)

[Volvo Trucks](#)



## Premium Tech Tool Compatible Adapter Matrix:

Revised: 5/4/2022					Volvo Truck													
Tech Tool 2.8.121					Electrical System Vehicle Production Diagnostic Connector	Version 3 (2013 to Present) 16-pin (OBD)					Version 2 (2002 - 2012) 9-pin (Deutsch)				Volvo Electronics '98 (1998 - 2002) 6-pin (Deutsch)		Volvo Legacy (Prior to 1998) 6-pin (Deutsch)	
					Adapter Connection Modes	Three Channel Communication (ISO-15765, J1939, J1587)	High Speed Programming	Standard Speed Programming	DTC Viewer - EPA 2010 Vehicles	VCADS Pro Diagnostics	High Speed Programming	Standard Speed Programming	DTC Viewer - EPA 2010 Vehicles	VCADS Pro Diagnostics	Standard Speed Programming (ECU)	VCADS Pro Diagnostics	Standard Speed Programming (ECU)	VCADS Pro Diagnostics
Communication Adapter	Current Driver/Firmware	*Windows 8.1 (Pro)	*Windows 10 (Pro)	*Windows 11 (Pro) - Testing														
= OK																		
= Not Supported																		
Pending Change - In Testing																		
* Windows should have latest updates for functionality and support																		
VOCOM II Tough (88894000)	v4.7.0.1157	OK	OK	OK	USB & Wireless	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
VOCOM II Mini (88894200)	v4.7.0.1157	OK	OK	OK	Wireless	OK	OK	OK	OK	OK	OK	OK	OK	NS	NS	NS	NS	NS
VOCOM (88890300)	v2.5.0.0	OK	OK	OK	USB & Wireless	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
88890020	v2.5.0.0	OK	OK		USB & Wireless	NS	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
Dearborn DPA IV+	v2.2.0.0	OK	NS		USB	NS	NS	NS	NS	NS	OK	OK	OK	OK	OK	NS	NS	NS
Dearborn DPA V (Dual CAN/Quad CAN/Pro)	v5.01	OK	OK		USB & Bluetooth	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK	OK	OK	OK
Drew Tech DrewLinQ	v1.1.27	OK	OK		USB	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK	OK	OK	OK
Nexiq USB-Link 2	v2.8.0.4	OK	OK		USB & Wireless/Bluetooth	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK	OK	OK	OK
Nexiq USB-Link	v9.6.0.2	OK	OK		USB & Bluetooth	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK	OK	OK	OK
Noregon DLA+ 2	v4.0.7445.1	OK	OK		USB	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK	OK	OK	OK
Noregon DLA+	v4.0.7005.1	OK	OK		USB	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK	OK	OK	OK
Noregon DLA+ Wireless 2	v4.0.7445.1	OK	OK		USB & Wireless	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK	OK	OK	OK
Noregon DLA+ Wireless	v4.0.7005.1	OK	OK		USB & Wireless	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK	OK	OK	OK
Noregon DLA+ PLC	v4.0.6829.2	OK	OK		USB	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK	OK	OK	OK

# MACK TRUCKS

## Service News



### Premium Tech Tool Compatible Adapter Matrix:

Revised: 5/4/2022				MACK Truck											
Tech Tool 2.8.121				Electrical System											
				Vehicle Production				VMAC-IV+ (2013 to Present)				VMAC-IV (2002 - 2012)			
Diagnostic Connector				16-pin (OBD)				9-pin (Deutsch)				6-pin (Deutsch)			
Communication Adapter				Adapter Connection Modes											
Current Driver/Firmware		*Windows 8.1 (Pro)	*Windows 10 (Pro)	*Windows 11 (Pro) - Testing	Three Channel Communication (ISO-15765, J1939, J1587)	High Speed Programming	Standard Speed Programming	DTC Viewer - EPA 2010 Vehicles	VCADS Pro Diagnostics	High Speed Programming	Standard Speed Programming	DTC Viewer - EPA 2010 Vehicles	VCADS Pro Diagnostics	Standard Speed Programming (ECU)	VCADS Pro Diagnostics
= OK															
= Not Supported															
Pending Change - In Testing															
* Windows should have latest updates for functionality and support															
VOCOM II Tough (88894000)	v4.7.0.1157	OK	OK	OK	USB & Wireless	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
VOCOM II Mini (88894200)	v4.7.0.1157	OK	OK	OK	Wireless	OK	OK	OK	OK	OK	OK	OK	OK	NS	NS
VOCOM (88890300)	v2.5.0.0	OK	OK	OK	USB & Wireless	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
88890020	v2.5.0.0	OK	OK		USB & Wireless	NS	OK	OK	OK	OK	OK	OK	OK	OK	OK
Dearborn DPA IV+	v2.2.0.0	OK	NS		USB	NS	NS	NS	NS	NS	OK	OK	OK	OK	OK
Dearborn DPA V (Dual CAN/Quad CAN/Pro)	v5.01	OK	OK		USB & Bluetooth	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK
Drew Tech DrewLinQ	v1.1.27	OK	OK		USB	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK
Nexiq USB-Link 2	v2.8.0.4	OK	OK		USB & Wireless/Bluetooth	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK
Nexiq USB-Link	v9.6.0.2	OK	OK		USB & Bluetooth	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK
Noregon DLA+ 2	v4.0.7445.1	OK	OK		USB	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK
Noregon DLA+	v4.0.7005.1	OK	OK		USB	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK
Noregon DLA+ Wireless 2	v4.0.7445.1	OK	OK		USB & Wireless	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK
Noregon DLA+ Wireless	v4.0.7005.1	OK	OK		USB & Wireless	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK
Noregon DLA+ PLC	v4.0.6829.2	OK	OK		USB	OK	NS	OK	OK	OK	NS	OK	OK	OK	OK